DEPARTMENT OF ENVIRONMENT
AND CONSERVATION
DIVISION OF SOLID WASTE
MANAGEMENT

5TH FLOOR, L&C TOWER
401 CHURCH STREET
NASHVILLE, TN 37243-1535

SOLID WASTE DISPOSAL FACILITY
Post-Closure Inspection

NAME OF SITE	REGISTRATION NUMBER	DATE
Perry Henry County Sanitary Landfill	SWL 40-101-0151	12-10-13
LOCATION (physical) 1140 Jones Bend Road	PURPOSE (✓) Complete ( ) Follow-up ( ) Consultation ( ) Complaint ( ) Other	
OWNER/OPERATOR Johnny Berry	TYPE OF FACILITY (✓) Class I ( ) Class II ( ) Class III ( ) Class IV	

		V1	V2
FINAL COVER			
–Unsatisfactory final cover (sloughing, cracks, etc.)	9010		
–Pooling of water	9020		
–Unsatisfactory stabilization of cover	9030		
EROSION/SEDIMENT CONTROL			
–Inadequate erosion control	9040		
–Washout of solid waste	9050		
RUN-ON/RUN-OFF CONTROL			
–Inadequate maintenance of run-on/run-off systems(s) (ponds, ditches, etc.)	9060		
LEACHATE CONTROL			
–Leachate observed at site	9070		
–Leachate entering run-off	9080		
–Leachate entering a water course	9090		
–Inadequate maintenance of leachate collection and removal system	9110		
GASMANAGEMENT SYSTEM			
–Inadequate gas migration control system	9120		
–Inadequate maintenance of gas migration control system	9130		
GROUNDWATER MONITORING SYSTEM			
–Groundwater monitoring system improperly maintained	9140		
–Groundwater protection standard violated	9150		
–Unapproved/inadequate groundwater monitoring methods	9160		
SITE ACCESS			
–Inadequate artificial or natural barrier	9170		
GENERAL			
–Facility does not correspond with permit condition(s)	9180		

COMMENTS:

No Violations Found

PERSON INTERVIEWED (Signature) Johnny Berry	INSPECTED BY (Signature) [illegible]
TITLE	TITLE Environmental Specialist

TIME OF DAY 1231	WEATHER CONDITIONS 31°F, Sunny	COMPLIANCE DATE

(Rev. 1-96) Distribution: White–Field Office Canary–Central Office Pink–Facility RDA 2202